| Scope of | Work for Property Lo | cated at: | | 4926 North 52nd Street | |
|------------------|------------------------------------|------------------|------------|--|------------|
| | Property is: Single Far | nily 🗹 🛭 | Duplex | □ Other □ | |
| Date: | 2/11/2015 | <u> </u> | | | |
| take no respo | onsibility for problems discovered | after the inspec | ction date | The City of Milwaukee, the Redevelopment Authori, or for omissions through error or oversight. The lis ral Block Grant or HOME programs. | • |
| Exterior | Condition Report | | | | |
| Location Site | Required Work Landscaping | n/a ☑ Y | ′es 🔲 | Note/Comments Self Help | Cost \$ |
| | Steps/Handrails | n/a ☑ Y | ′es 🗌 | | \$ |
| | Service walks | n/a ☑ Y | ′es 🗌 | | \$ |
| | Fencing | n/a 🔲 Y | ′es ✓ | | \$ 250.00 |
| | Parking | n/a ✓ Y | ′es 🗌 | | \$ |
| | Retaining walls | n/a ☑ Y | ′es 🗌 | | \$ |
| | Other | n/a 🔲 Y | ′es 🗌 | | \$ |
| | Other | n/a 🔲 Y | ′es 🗌 | | \$ |
| Garage | Singles: repair | n/a 🗌 Y | ′es 🗌 | | \$ |
| | Shingles: Roof over existing | n/a 🗌 Y | ′es 🗌 | | \$ |
| | Shingles:Tear off & re-roof | n/a 🗌 Y | ′es 🗌 | | \$ |
| | Gutters/downspouts | n/a 🔲 Y | ′es 🗌 | | \$ |
| | Flashing | n/a 🗌 Y | ′es 🗌 | | \$ |
| | Eaves | n/a 🔲 Y | ′es 🗌 | | \$ |
| | Siding | n/a □ Y | ′es 🗌 | | \$ |
| | Doors | n/a 📗 Y | ′es 🗌 | | \$ |
| | Windows | n/a □ Y | ′es 🗌 | | \$ |
| | Slab | n/a 🔲 Y | ′es 🗌 | | \$ |
| | Paint | n/a □ Y | ′es 🗌 | | \$ |
| | Electrical | n/a 🔲 Y | ′es 🗌 | | \$ |
| | Other | n/a □ Y | ′es 🗌 | | \$ |
| Porches | Roof | n/a ☑ Y | ′es 🗌 | | \$ |
| | Deck-upper | n/a ☑ Y | ′es 🗌 | | \$ |
| | Decklower | n/a ☑ Y | ′es 🗌 | | \$ |
| | Steps/handrails | n/a ☑ Y | ′es 🗌 | - | \$ |
| | Ceiling | n/a ☑ Y | ′es 🗌 | | \$ |
| | Guardrails | n/a ☑ Y | ′es 🗌 | | \$ |
| | Structural | n/a ☑ Y | ′es 🗌 | | \$ |
| | Paint | n/a ☑ Y | ′es 🗌 | | \$ |
| | Other | n/a 🔲 Y | ′es 🗌 | | \$ |
| | - | | | | |

House

| Chimney | n/a ☑ Yes 🗌 | \$ |
|------------------------------|---------------------------|--------------|
| Shingles: repair | n/a ☑ Yes 🗌 | \$ |
| Shingles: Roof over existing | n/a ☑ Yes 🗌 | \$ |
| Shingles:Tear off & re-roof | n/a ☑ Yes 🗌 | \$ |
| Gutters/downspouts | n/a ☑ Yes 🗌 | \$ |
| Flashing | n/a ☑ Yes 🗌 | \$ |
| Eaves | n/a ☑ Yes 🗌 | \$ |
| Siding | n/a ☐ Yes ☑ Repair | \$ 400.00 |
| Storm Doors | n/a ☐ Yes ☑ | \$ 150.00 |
| Prime ("main") Doors | n/a ☑ Yes 🗌 | \$ |
| Storm Windows | n/a ☑ Yes 🗌 | \$ |
| Prime ("main") Windows | n/a ☑ Yes 🗌 | \$ |
| Paint | n/a ☐ Yes ☑ Trim | \$ 950.00 |
| Foundation | n/a ☑ Yes 🗌 | \$ |
| Electrical | n/a ☑ Yes 🗌 | \$ |
| Other | n/a 🗌 Yes 🗍 | \$ |
| Other | n/a 🗌 Yes 🗍 | \$ |
| Other | n/a Yes | \$ |
| Other | n/a Yes | \$ _ |

Exterior: Estimated Cost:* \$ 1,750.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

| Interior Co | ondition Report | | | | | | |
|-------------|--|--------|----------|-----|----------|--|----------------|
| | Unit: Entire unit (single family) Upper unit of duplex | ✓ □ | | | | Lower unit of duplex Other | |
| | Required Work | | | | | | |
| Heating | Repair/replace boiler | n/a | v | Yes | П | | \$ |
| | | | | | _ | | |
| | Repair radiation | n/a | ✓ _ | Yes | <u>Ц</u> | | \$ |
| | Repair/replace furnace | n/a | ✓ | Yes | | | \$ |
| | Repair ductwork | n/a | ✓ | Yes | | | \$ |
| | Replace thermostat | n/a | ✓ | Yes | | | \$ |
| | Repair/replace grilles | n/a | V | Yes | | | \$ |
| Electrical | Tune boiler/furn. insp ht exchang | en/a | | Yes | V | | \$ 325.00 |
| | Repair/replace receptacles | n/a | V | Yes | | | \$ |
| | Repair/replace switches | n/a | V | Yes | | | \$ |
| | Repair/replace fixtures | n/a | V | Yes | | | \$ |
| | Install outlets and circuits | n/a | | Yes | V | | \$ 200.00 |
| | Install outlets and circuits | n/a | | Yes | V | GFCI | \$ 600.00 |
| | Install outlets and circuits | n/a | V | Yes | | | \$ |
| | Install outlets and circuits | n/a | V | Yes | | | \$ |
| | Upgrade service | n/a | V | Yes | | | \$ |
| | Other | n/a | | Yes | V | Repair wiring and devices to be code compliant | \$ 500.00 |
| | Other | n/a | | Yes | | | \$ |
| Plumbing | Repair/replace kitchen sink | n/a | V | Yes | | | \$ |
| | Repair/replace kitchen sink fauce | n/a | V | Yes | | | \$ |
| | Repair/replace tub | n/a | | Yes | | | \$ |
| | Repair/replace tub faucet | n/a | | Yes | | | \$ |
| | Repair/replace toilet | n/a | | Yes | | | \$ |
| | Repair/replace lavatory | n/a | | Yes | | | \$ |
| | Repair/replace lavatory faucet | n/a | | Yes | | | \$ |
| | Repair/replace wash tub | n/a | | Yes | | | \$ |
| | Repair/replace wash tub faucet | n/a | | Yes | | | \$ |
| | Unclog piping: | n/a | V | Yes | | | \$ |
| | Repair drain/waste/vent piping | n/a | V | Yes | | | \$ |
| | Repair water piping | n/a | V | Yes | | | \$ |
| | Repair/replace water heater | n/a | | Yes | V | | \$ 950.00 |
| | Other | n/a | | Yes | ▽ | Complete Bath, Lavatory,Tub, Toilet | \$ 2,200.00 |
| | | | | | | | |

Other

\$

| Windows | | | | | | | | | | | |
|---------------|----------------------------------|------|--------------|-----|----------|--|----|----------|--|--|--|
| | Replace broken glass | n/a | ✓ | Yes | | | \$ | | | | |
| _ | Repair or replace sash | n/a | √ | Yes | | | \$ | | | | |
| Doors | Repair or replace doors | n/a | V | Yes | | | \$ | | | | |
| | Repair or repl. locks/latches | n/a | | Yes | V | Self Help | \$ | 110.00 | | | |
| Walls/Ceiling | • | | | | | | | | | | |
| | Repair or repl. @ defective | n/a | | Yes | ✓ | | \$ | 1,400.00 | | | |
| Paint | Repair or repl. @ defective | n/a | | Yes | v | | \$ | 570.00 | | | |
| Fine Onfoto | Tropair or repr. & derective | 11/U | | 100 | Ľ | | Ψ | 370.00 | | | |
| Fire Safety | Install smoke/CO alarm:bsmt. | n/a | | Yes | V | Self Help | \$ | 55.00 | | | |
| | Install smoke/CO alarm: 1st flr. | n/a | | Yes | V | Self Help | \$ | 55.00 | | | |
| | Install smoke/CO alarm: 2nd flr. | n/a | \checkmark | Yes | | Self Help | \$ | | | | |
| Handrails | | | | | | - | | | | | |
| Ctains | Repair/replace defective | n/a | √ | Yes | | Self Help | \$ | | | | |
| Stairs | Repair defective | n/a | | Yes | V | Basement | \$ | 700.00 | | | |
| Floors | | , | _ | ., | _ | | • | | | | |
| Other | Repair defective | n/a | Ш | Yes | ✓ | | \$ | 400.00 | | | |
| ouio. | | n/a | | Yes | | | \$ | | | | |
| | | n/a | | Yes | | | \$ | | | | |
| | | n/a | | Yes | | | \$ | | | | |
| | | | | | | Interior: Estimated Cost: | \$ | 8,065.00 | | | |
| | | | | | | Total Exterior and Interior Cost:* | \$ | 9,815.00 | | | |
| | | | | | | *average contracted cost. Actual costs may vary. Self help will reduce the amount. | | | | | |

Inspected by: Martin Kleiber Date: 2/11/2015

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.